Date: 4 March 2002

For the
Inspect and Repair Only As Necessary (IROAN)
Of the
Light Armored Vehicle (LAV-25)
Thermal Sight System
Aux/Bias Circuit Card Assembly
NSN 5998-01-438-5415

SOW-04-PM-LAV-8H732B-2/1

- 1. No Statement Of Work (SOW) is required to IROAN the Aux/Bias CCA, NSN 5998-01-438-5415, Part Number 6245810. The Marine Corps lack the necessary technical data for repair, and the technical data is proprietary to the Original Equipment Manufacturer (OEM). This is a commercially repaired item that has to be returned to the OEM.
- 2. The following points of contact apply:

Randy Geoghagan Equipment Specialist Program Manager Light Armored Vehicles-Albany MARCORSYSCOM, Albany, Ga.

Carolyn Mayberry
Inventory Management Specialist
Supply Chain Management Center
Combat Ground Weapons Branch Code 576-3
MARCORLOGBASES, Albany, Ga.